


Item Replacement Notice Flapper THU499S

Current THU499S



Replacement THU500S



Product No.	REPLACEMENT Product No.	UPC	List Price	Description
THU499S	THU500S	739268326958	\$15	Replacement Flapper

Important Note

There is limited inventory of THU499S. Once this inventory has been depleted it will be discontinued. Replacement item THU500S will be available after THU499S is depleted.