

## Item Replacement Notice **EFFECTIVE IMMEDIATELY** Undercounter Lavatory Mounting Hardware THU077, THU230, & THU709

THU077, THU230, & THU790 have limited inventory and will be discontinued.

The replacement item numbers are: **THU408, THU409, & THU473**

The affected undercounter lavatory model numbers are provided below:

UNDERCOUNTER LAVATORY MODELS								
THU408						THU409		THU473
LT156	LT481	LT533	LT577	LT624	LT931	LT181	LT546	LT191
LT221	LT483	LT540(G)	LT587	LT626	LT967		LT548	
LT231	LT491	LT542(G)	LT579(G)	LT641	LT973	LT183	LT553	LT193
LT233		LT569	LT597(G)	LT643				

**Discontinued Item Details:**

Product No.	UPC	List Price
<b>THU077</b>	73926430273	\$18
<b>THU230</b>	739268044388	
<b>THU709</b>	739268163225	

**New - Replacement Items Details:**


Product No.	UPC	List Price
<b>THU408</b>	<b>739268318991</b>	<b>\$18</b>
<b>THU409</b>	<b>739268319004</b>	
<b>THU473</b>	<b>739268319202</b>	

Hardware for Granite or Marble countertop installations must be purchase separately

<b>THU410</b>	<b>739268319012</b>	<b>\$16</b>
---------------	---------------------	-------------



Included



Included



Included



Must be purchased separately for granite/marble countertop installations

